

### গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

# ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	মেমার্স গুড গাইম লিঃ
ঠিকানা	J–L–12, Dag # 505, 554, Bailjury,Turag, Uttara, Dhaka
কারখানার কোড	DHK234
কালার কোড	

	া: কাঠামোগত মূল্যায়ন	পর্ববেক্ষণের তারিখ: 🌼	<u>9-08-20</u>
পর্ববেষ্ফণ			
পরিদর্শন পর্ববেষ্ষণ	s build design drawing		
ক্যাপ আইটেম ক্যোটিল			
ক্যাটাগরি			
১.১. কাৰ্যক্ৰম	1		
কাৰ্শক্ৰম	structural elements and foundation of Detailed Engineering Assessment ( Di with in six monthes. If DEA is not don	Instruct a as build drawing of the differ the building with in six weeks in this EA) is required immediately and comp e with in this period, appropriate mea r General of Factories and Establishme	process plete sures to
সুপারিশের তখ্যসূত্র			
কার্থানার কার্বক্রম			
অগ্রাধিকার	৬ সপ্তাহ		
চুডান্ড সমশ্রসীমা	_		
সংশোধিত সময়সীমা	%€-0₽-3033		
অগ্রগতির অবস্থা	চলমাল		
মন্তব্য	completion certificate also got from the observation: All design & drawings are completion certificate also got from the drawing approved. DEA completion completion completion completion for clearance certificate from drawings were approved from DIFE Remanagement have got Business as US Structural. 21/08/2022: All drawings drawings need to be updated. 03/04 DIFE but As built drawings need to be	e submitted to DIFE without any retroine consultancy firm. 09.11.2020: All descrificate got from consulting firm. the DIFE. 31.08.2021: All Structural design CC without any retro-fication. The factural Certificate from DIFE on 01/11/20 have been approved by DIFE but As be 1/2023: All drawings have been approved.	fit. DEA esign by are n & tory 020 for built
সংযুক্তি ×	मभूर (२)		

Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual'. 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		
ান্ধৰ্মন নিৰ্বেচন চাট্টাপ্তৰি  The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  স্পাৰিশ্বৰ ভ্ৰম্যুত্ৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ	পৰ্যবেষ্ফণ	
ান্ধৰ্মন নিৰ্বেচন চাট্টাপ্তৰি  The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  স্পাৰিশ্বৰ ভ্ৰম্যুত্ৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ বিশ্বৰ ভ্ৰমুত্ৰ বিশ্বৰ	विद्यंत ।	
ি.১. কাৰ্যক্ৰম  The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  স্পানিশেন জ্বাসুত্ৰ কাৰখানাৰ কৰ্মাসুত্ৰ কৰ্মাসুত্ৰ কাৰখানাৰ কৰ্মাসুত্ৰ কৰ্মাস	।। ব্যবেষ্দ্রন In	tensity of floor loading
াইটেন চ্যাটাগনি  The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  মুগারিশের ভণ্যসূত্র কারখানাব কার্যক্রম জ্ঞামিকার ৬ সপ্তাহ্য ভূতান্ত সমবসীমা সংলোখিত সমবসীমা ব্যাপিত বিশ্বতি তি ত		
The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  মুগারিশের ভীমুত্র কার্যানার কার্যক্রম আমানিকার ৬ সন্তাহ ভূতাত্ত সমস্বসীমা আম্মানিকার আমানিকার		
The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  স্পানিশ্বে ভাগ্যমূত্ৰ কাৰখানাৰ কাৰ্যক্ৰম  আমানিকাৰ  সংলাধিত  মনবামা  নংলাধিত  মানবামা  নংলাধিত  মানবামা  নংলাধিত  আমানিকাৰ  মংলাধিত  মংলাধিত  আমানিকাৰ  মংলাধিত  আমানিকাৰ  মংলাধিত  মংলাধিত  মংলাধিত  আমানিকাৰ  মংলাধিত  মংলা		
The factory owner is asked to shift all storage of ground floor immediately. More over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  স্পানিশেন ভিম্মুত্ৰ কাৰণান কাৰ্য্যনান কাৰ্যনান কাৰ্		
over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  মূলানিশেষ ভথ্যসূত্ৰ কাৰখানাৰ কাৰ্ড্ৰম জ্ঞানিকাৰ ৬ সপ্তাহ ডুডান্ত সম্বামীমা স্ম্যোখিভ  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual'. 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also	.১. কাৰ্যক্ৰ	4
over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).  মূলানিশেষ ভথ্যসূত্ৰ কাৰখানাৰ কাৰ্ড্ৰম জ্ঞানিকাৰ ৬ সপ্তাহ ডুডান্ত সম্বামীমা স্ম্যোখিভ  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual'. 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		The factory owner is nelved to shift all store so of averaged floor improdictally. Mare
কাৰণানাৰ কাৰ্যক্ৰম জ্ঞাধিকাৰ ৬ সপ্তাহ টুড়ান্ত সমস্বসীমা জ্ঞাজিৰ জ্বৰম্ম  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		over the consultant strongly recommend storing any type of cartoon boxes, finished products and fabrics in such a manner so that intensity of loading should not exceed 60 psf (3KN/m2).
কাৰ্যনান কৰ্যক্ষ জ্ঞাধিকাৰ ৬ সপ্তাহ চূড়ান্ত সম্বসীমা সংশোধিত সম্বসীমা জ্ঞান্তিৰ অবস্থা  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		
ৰাজ্য বিদ্যান		
মুখ্যম্বাসীয়া সংশোধিত সম্বৰ্মীয়া অঞ্জতিৰ অবস্থা  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		
সমধ্যমীমা সংশোধিত সমধ্যমীমা অঞ্জি অবস্থা  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also	অগ্রাধিকার	৬ সপ্তাহ
সংশাধিত সমর্যসীমা  আঞ্চাতিব আবস্থা  11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2).The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2).The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also	চুডান্ড সময়সীমা	-
11/02/2020: No over loading found on the floors. Load plans are also posted on walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		26-0P-≤0≤≤
walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual'. 03/04/2023: No overload was found during inspection date. The DEA report has received approval from DIFE and also		সংশোধিত
received 'Certificate of Business as Usual' .		walls. 13.07.2020 Visit observation: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 60 psf (3KN/m2). The factory management have followed the approved floor load plan. 09.11.2020: Over loading has not been found on the floors. Load plans are also posted on walls. All floors loading found under 42 psf (2KN/m2). The factory management have followed the approved floor load plan. 31.08.2021: No overloading found on any upper tier floors to Ground floor during inspection. Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: No overload was found during inspection date. The DEA report has received approval from DIFE and also received 'Certificate of Business as Usual' . 03/04/2023: No overload was found
	X X	সমূহ (8) ×

পরিদর্শন   পর্ববেষ্ণনা			
ক্যাপ	ক্যাপ		
আইটেম			
ক্যাটাগরি			
৩.১. কাৰ্যক্ৰ	7		
	No horizontal and vertical extension shall be made with out detail investigation and		
   কাৰ্যক্ৰম	no further construction is to be carried out on this building untill Detail Engineering		
	Assessment (DEA) is completed.		
সুপারিশের	Absessment (BEA) is completed.		
ভিখ্যসূত্র			
কারখানার কারখানার			
কাৰ্যক্ৰম			
অগ্রা <u>খি</u> কার	KIIZ 4/		
<u> চুডান্ড</u>			
্যুড়াড় সময়সীমা	-		
সংশোধিত			
সময়সীমা	08-05-2050		
<u>অগ্রগতির</u>			
অবস্থা	সংশোধিত		
	11/02/2020: Not applicable. No horizontal and vertical extension found on the		
	visiting date. 13.07.2020 Visit observation: No vertical horizontal extension.		
মন্তব্য	09.11.2020: No horizontal and vertical extension 31.08.2021: No horizontal and		
	vertical extension found on the visiting date. 21/08/2022: No Horizontal and		
	Vertical Extension was found during inspection date. 03–04–2023: Completed.		
সংস্ক্রিসমূহ (৪)			

### ৪. পর্যবেষ্ণণ

পরিদর্শন পর্ববেষ্ফণ	oor load plan
ক্যাপ আইটেম ক্যাটাগরি	
৪.১. কাৰ্যক্ৰ	51 51
0.0. 1114	1
কাৰ্শক্ৰম	The factory owner has to prepar and submit the load plan for all floors with in three weeks for approval and has to arrange displaying the vetted load plan of each floor on the wall in a conspicuous location.
সুপারিশের ভখ্যসূত্র	
কারখানার কার্যক্রম	
অগ্রাধিকার	থবোজ্য ন্য
চুডান্ড সমশ্রসীমা	_
সংশোধিত সময়সীমা	26-04-5055
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	11/02/2020: All design & drawings are submitted to DIFE without any retrofit. DEA completion certificate also got from the consultancy firm. Load plans are also posted on walls. 13.07.2020 Visit observation: All design & drawings are submitted to DIFE without any retrofit. DEA completion certificate also got from the consultancy firm. Load plans are also posted on walls. 09.11.2020: Factory management has posted approved floor load plan in all entrance visible place. 31.08.2021: Load plan posted on walls of each floor. Loading found under 60 psf (3KN/m2) on each floor. All Structural design & drawings were approved from DIFE RCC without any retro-fication. The factory management have got Business as Usual Certificate from DIFE on 01/11/2020 for Structural. 21/08/2022: Load plan was found posted on walls of each floor during inspection date. 03/04/2023: Load plan was found posted on walls of each floor during inspection date.
সংযুক্তি × ×	সমূহ (8) ×

# <u>৬</u>. পর্যবেষ্ণণ

পরিদর্শন পর্শবেষ্কণ	Distress in primary structural elements
ক্যাপ আইটেম ক্যাটাগরি	

#### ৫.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম	The owner or user of the building should be vigiland about development of any distress, particularly in primary structural elements of the building. If cracks appear, propagate and widen, detailed assessment and adoption of remedial measures may become necessary.	
সুপারিশের তথ্যসূত্র		
কারখানার কার্যক্রম		
অগ্রাধিকার	৬ মাস	
চুডান্ড সময়সীমা	_	
সংশোধিত সমশ্রসীমা	08-0%-2059	
অগ্রগতির অবস্থা	সংশোধিত	
মন্তব্য	11/02/2020: Not applicable. No distress found in any primary structural elements. 13.07.2020 Visit observation: No distress in primary structure has been found on visit date. 09.11.2020: No distress in primary structural elements has been found in visiting date. They done color coating in all floor wall. 31.08.2021: No distress found in any primary structural elements on the visiting date. 21/08/2022: No Distress in Primary Structural Element was found during inspection date. 03/04/2023: No Distress in Primary Structural Element was found during inspection date.	
সংযুক্তি ×	ममूर् (२)	