

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয়

শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

## ক্যাপ পর্যবেষ্ফণের তথ্য

কারখানার নাম	সাকওয়ান আউটওয়ার লিমিটেড
ঠিকানা	Zirabo, DEPZ Road, Ashulia, Savar, Dhaka
কারখানার কোড	DHK510
কালার কোড	

মুল্যায়নের ধরণ: কাঠামোগত মুল্যায়ন	পর্যবেষ্ফণের তারিখ: ২৪–০৮–২০২
১. পর্যবেষ্ণ্য	

পরিদর্শন পর্শবেষ্ষণ	Absence of approval drawings
ক্যাপ আইটেম	
ক্যাটাগরি	•

১.১. কার্বক্রম		
ক	<b>া</b> ৰ্যক্ৰম	As-built architectural and structural drawings to be prepared for both sheds and submitted for approval by appropriate authority. As part of this process the building engineer will be required to make a number of checks on the structural design.
ভ	পারিশের খ্যসূত্র	
ক	ার্খানার <u>বিক্রম</u>	We have not taken action but it will be implemented within final timeline.
অ	গ্রাধিকার	প্রযোগ্য নর
স্ট	ড়ান্ত নর্মীমা	75-77-5070
স্থ	ংশোধিত নয়সীমা	07-07-7940
	গ্রগতির বস্থা	চলমান
घार	ষ্ট <b>ব্য</b>	Previous timeline: 21–09–2016 Final Timeline: 12/11/2017 Factory has not taken action but they have agreed to implement within final timeline. On 22/01/2020: Factory management contact DIFE's enlishted firm to complete this issue. Engaged consulting firm submit requied drawing to DIFE for approval. On 14/09/2020: As built structural drawing, as built architectural drawing and Rectrofit structural drawing submitted to DIFE on 28/07/2018 which is not approved yet. Drawing Design was not found in site. 08.12.20 Visit observation: As built structural drawing, as built architectural drawing and Rectrofit structural drawing submitted to DIFE on 28/07/2018 which is not approved yet. They are waiting for approval and they want to do remidiational work. Drawing Design was not found in site. 10/08/2021 Visit observation: All structural design & drawings were re-submitted to DIFE RCC on 20/02/2020 after 77th Structural taskforce meeting held on 03/12/2018. After this re-submission no structural taskforce meeting held regarding this factory. Now the factory management is waiting for taskforce decision. 24/08/2022: As-built architectural and structural drawings should be prepared and resubmitted to DIFE for approval as soon as possible.

সংখুক্তিসমূহ (२) × ×

পরিদর্শন পর্শবেষ্ফণ	Lack of lateral stability system
ক্যাপ আইটেম ক্যাটাগরি	

## ২.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম	The frame needs to be checked by building engineer. The lateral system is required to ensure the stability of structure and carry out any remedial actions as directed by the Building Engineer for lateral stability system.
সুপারিশের তখ্যসূত্র	
কার্থানার কার্বক্রম	We have not taken action but it will be implemented within final timeline.
অগ্রাধিকার	প্র্যোগ্য নয়
চুডান্ড সমশ্বসীমা	75-77-507d
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	চলমান
মন্তব্য	Previous timeline: 12–02–2017 Final Timeline: 12/11/2017 Factory has not taken action but they have agreed to implement within final timeline. On 22/01/2020: Factory management contact DIFE's enlishted firm to complete this issue. Engaged consulting firm submit requied drawing to DIFE for approval. On 14/09/2020: Status same as last visit. 08.12.20 Visit observation: As built structural drawing, as built architectural drawingsubmitted to DIFE on 28/07/2018 which is not approved yet. The factory have no building engineer to check the lateral stability of the structure. 10/08/2021 Visit observation: All structural design & drawings were resubmitted to DIFE RCC on 20/02/2020 after 77th Structural taskforce meeting held on 03/12/2018. After this re–submission no structural taskforce meeting held regarding this factory. Now the factory management is waiting for taskforce decision. 22/08/2022: DEA report should be prepared and resubmitted to DIFE as soon as possible.
সংযুক্তি ×	म्पूर (२)