



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখালা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

মুরগ্কা নিবন্ধন নিশ্চিত করণ

ক্যাপ পর্যবেক্ষণের তথ্য

কারখালার নাম	এস আর বি ক্যাপলস লিঃ
ঠিকানা	13448, Satarkul Bazar,
কারখালার কোড	DHK562
কালার কোড	

মূল্যায়নের ধরণ: বৈদ্যুতিক মূল্যায়ন

পর্যবেক্ষণের তারিখ: ২৩-০১-২০২৩

১. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	Improper separation □ Access to substation not easy □ Ventilation and illumination of substation is poor □ Separating wall not extended up to the ceilingt □ No clear identification mark on distribution panel □ No instruction for first aid to electrical shock and artificial respiration □ Non-conductor mat not provided/ insufficient □ Electric cables do not pass through service shaft or insulated conduits .
কাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম

কার্যক্রম	□ Provide easy access to the substation □ Produce design drawings to demonstrate the incorporation of fire rated enclosure and an approved fire rated door for the Substation room. □ Provide clear identification mark on distribution panel.
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	2016-07-11 00:00:00
অধিকারী	ধৰ্মেজ্য লেখ
চূড়ান্ত সময়সীমা	১৫-০৮-২০২২
সংশ্লাধিত সময়সীমা	০১-০১-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	20-09-2020: Fire door installation on processing from next week. And also this cap is related with fire cap issue. 10-12-2020: Fire door installation on processing. And also this cap is related with fire cap issue. 03-03-2021: Fire door installation on processing. And also this cap is related with fire cap issue. 05-05-2021: 1. Substation room is found to be accessible. 2. Design drawings for fire separation was submitted but not approved yet. 3. Clear identification mark were missing for some distribution boards. 03-08-2022 visit observation: 1. Substation room were found accessible. 2. Design drawings for fire separation was submitted but not approved yet. 3. Clear identification mark were found missing some distribution boards. 23-01-2023 visit observation: 1. Substation room were found accessible. 2. Design drawings for fire separation was submitted but not approved yet. 3. Clear identification mark were found missing some distribution boards.

সংযুক্তিমূহ (8)



২. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	Improper separation □ Access to substation not easy □ Ventilation and illumination of substation is poor □ Separating wall not extended up to the ceilingt □ No clear identification mark on distribution panel □ No instruction for first aid to electrical shock and artificial respiration □ Non-conductor mat not provided/ insufficient □ Electric cables do not pass through service shaft or insulated conduits .
কাপ আইটেম ক্যাটাগরি	

২.১. কার্যক্রম

কার্যক্রম	□ Provide fire rated enclosure and approved fire rated door for the Substation room. □ Install appropriate detectors
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	26-03-2017
অণ্টার্থিকার	৬ মাস
চূড়ান্ত সময়সীমা	০৪-০৯-২০২৩
সংশোধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলগাল
মন্তব্য	20-09-2020: Fire door installation on processing from next week. And also this cap is related with fire cap issue. 10-12-2020: Fire door installation on processing. And also this cap is related with fire cap issue. 03-03-2021: Fire door installation on processing. And also this cap is related with fire cap issue. 05-05-2021: 1. Fire rated door was not found for the substation room to segregate it from the rest of the occupancy. 2. Appropriate detectors were not installed. 3. Insulated rubber mat were not found, instead non-graded rubber mat found. 4. Cables passes through insulated conduits. 03-08-2022 visit observation: 1. Fire rated enclosure and approved fire rated door for the substation room were not found. 2. Appropriate detectors were not found. 3. Proper fire separation were not found. 23-01-2023 visit observation: 1. Fire rated enclosure and approved fire rated door for the substation room were not found. 2. Appropriate detectors were not found. 3. Proper fire separation were not found.
সংযুক্তিমূহ (8)	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>

৩. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	Improper separation of substation not easy Ventilation and illumination of substation is poor Separating wall not extended up to the ceiling No clear identification mark on distribution panel No instruction for first aid to electrical shock and artificial respiration Non-conductor mat not provided/ insufficient Electric cables do not pass through service shaft or insulated conduits .
কাপ আইটেম ক্যাটাগরি	

৩.১. কার্যক্রম

কার্যক্রম	Ensure accessibility and ventilation to substation Provide instructions for first aid and artificial respiration from exposure to electrical shock.
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	2016-03-10 00:00:00
অধ্যাধিকার	প্রযোজ্য নথি
চূড়ান্ত সময়সীমা	০৯-০৯-১৯৭০
সংশোধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলগাল
মন্তব্য	20-09-2020: Found accessibility and ventilation to substation room. 10-12-2020: Found accessibility and ventilation to substation room. 03-03-2021: Found accessibility and ventilation to substation room. 05-05-2021: 1. Accessibility and ventilation of the substation room is found to be adequate. 2. Instruction boards were found beside distribution boards but was missing in the substation room and generator room. 3. Insulated rubber mat were not found, instead non-graded rubber mat found. 03-08-2022 visit observation: 1. Accessibility and ventilation of the substation room is found to be adequate. 2. Instruction for first aid & artificial respiration boards were found missing some distribution board. 3. Electric grade Insulated rubber mat were not found. 23-01-2023 visit observation: 1. Accessibility and ventilation of the substation room is found to be adequate. 2. Instruction for first aid & artificial respiration boards were found missing some distribution board. 3. Electric grade Insulated rubber mat were not found.
সংযুক্তিমূহ (৬)	
<input checked="" type="checkbox"/>	

৪. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	<input type="checkbox"/> No instruction for first aid to electrical shock <input type="checkbox"/> Access obstructed/barred <input type="checkbox"/> No clear identification mark on distribution board
কাপ আইটেম ক্যাটাগরি	

৪.১. কার্যক্রম

কার্যক্রম	<input type="checkbox"/> Provide clear identification mark on distribution board.
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	2016-07-11 00:00:00
অধার্থিকার	প্রযোজ্য নথি
চূড়ান্ত সময়সীমা	১৫-০৮-২০২২
সংশ্লাধিত সময়সীমা	১৫-০৮-২০২২
অগ্রগতির অবস্থা	চলচ্চাল
মন্তব্য	20-09-2020: Found clear identification mark on distribution board. 10-12-2020: Found clear identification mark on distribution board. 03-03-2021: Found clear identification mark on distribution board. 05-05-2021: Clear identification mark for some distribution boards were missing. 03-08-2022 visit observation: Clear identification mark for some distribution boards were found missing. 23-01-2023 visit observation: Clear identification mark for some distribution boards were found missing.

সংযুক্তিমূহ (৪)



৫. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	<input type="checkbox"/> No instruction for first aid to electrical shock <input type="checkbox"/> Access obstructed/barred <input type="checkbox"/> No clear identification mark on distribution board
কাপ আইটেম ক্যাটাগরি	

৫.১. কার্যক্রম

কার্যক্রম	<input type="checkbox"/> Provide instructions for first aid from exposure to electrical shock <input type="checkbox"/> Remove obstruction to ensure access to MDB/MCB Box.
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	2016-03-10 00:00:00
অধার্থিকার	প্রযোজ্য নয়
চূড়ান্ত সময়সীমা	০৯-০৯-১৯৭০
সংশ্লাভিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	20-09-2020: Removed all obstruction to ensure access to MDB/MCB Box. 10-12-2020: Removed all obstruction to ensure access to MDB/MCB Box. 03-03-2021: Removed all obstruction to ensure access to MDB/MCB Box. 05-05-2021: 1. Instruction boards were found beside distribution boards but was missing in the substation room and generator room. 2. Distribution boards/MCC/MCB box were found to be accessible. 03-08-2022 visit observation: 1. Instruction for first aid to electrical shock were found missing some distribution board. 2. Some distribution boards were found obstructed & inaccessible. 23-01-2023 visit observation: 1. Instruction for first aid to electrical shock were found missing some distribution board. 2. Some distribution boards were found obstructed & inaccessible.
সংযুক্তিসমূহ (8)	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>

৬. পর্যবেক্ষণ

পর্যবেক্ষণ পর্যবেক্ষণ	<input type="checkbox"/> Electric cables do not pass through service shaft or insulated conduits
কাপ আইটেম ক্যাটাগরি	

৬.১. কার্যক্রম

কার্যক্রম	<input type="checkbox"/> Provide service ducts or insulated conduits
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	2016-07-11 00:00:00
অধিকারী	প্রযোজ্য লব
চূড়ান্ত সময়সীমা	১৫-০৮-২০২২
সংশোধিত সময়সীমা	১৫-০৮-২০২২
অংগতির অবস্থা	সংশোধিত
মন্তব্য	20-09-2020: Service ducts and insulated conduits found. 10-12-2020: Service ducts and insulated conduits found. 03-03-2021: Service ducts and insulated conduits found. 05-05-2021: Electric cables passes through insulated conduit. 03-08-2022 visit observation: Electric cables passes through service shaft or insulated conduit were found. 23-01-2023 visit observation: Electric cables passes through service shaft or insulated conduit were found.
সংযুক্তসমূহ (৮)	<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>

৭. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	<input type="checkbox"/> Lightning protection system not available
কাপ আইটেম ক্যাটাগরি	

৭.১. কার্যক্রম

কার্যক্রম	<input type="checkbox"/> Provide appropriate Lightning protection system.
সুপারিশের তথ্যসূত্র	
কারখনার কার্যক্রম	26-03-2017
অঞ্চলিকার	৬ গ্যাস
চূড়ান্ত সময়সীমা	০৪-০৯-২০২৩
সংশ্লাধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	20-09-2020: Approved design drawing found on site and LPS installation has been done. 10-12-2020: Approved design drawing found on site and LPS installation has been done. 03-03-2021: Approved design drawing found on site and LPS installation has been done. 05-05-2021: LPS was installed for the factory. 03-08-2022 visit observation: Approved LPS drawing were found & LPS Installation has been done. But some air terminal were missing & expose rubber were found. 23-01-2023 visit observation: Approved LPS drawing were found & LPS Installation has been done. But some air terminal were missing & expose rubber were found.
সংযুক্তসমষ্টি (৮)	
<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	