



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখালা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

মুরগ্কা নিবন্ধন নিশ্চিত করণ

ক্যাপ পর্যবেক্ষণের তথ্য

কারখালার নাম	ক্যাপিটাল ক্যাশলস লিঃ
ঠিকানা	Dilan Complex (Building-02), Dhaka Road, Chandona Chawrasta, Gazipur-1702.
কারখালার কোড	GZP063
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন	পর্যবেক্ষণের তারিখ: ১৬-০২-২০২৩
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	Cracks and dampness
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম

কার্যক্রম	Carry out repairing and remedial actions as directed by the Building Engineer for these cracks and dampness.
সুপারিশের তথ্যসূত্র	
কার্যক্রম কার্যক্রম	Factory has remediated all cracks and dampness observed during the assessment.
অগ্রাধিকার	৬ মাস
চূড়ান্ত সময়সীমা	-
সংশ্লাধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	<p>Capital Designs Ltd. has been replaced by Capital Fashions Ltd. Cracks have been found on masonry wall at different floor and in GF toilet zone. Some repairing works were found abruptly but crack investigation report was not available at site. Also, dampness was found on masonry wall at different floor. Water ponding was observed on roof top. 4th January 2021: Some non structural crack found on some partition wall at the time of inspection. Some repairing works were found abruptly but crack investigation report was not available at site. Dampness was found on masonry wall at different floor. Water ponding was observed on roof top.</p> <p>13.04.2021: No major cracks were found only some hairline masonry cracks on the walls and dampness were seen on several places like the women's toilet on 2nd floor and men's toilet on 2nd floor. 19th August 2021: No major cracks found in primary structural elements. Dampness found in several places. 3rd August 2022: During visit date non structural wall crack found on the building. some cracks they are remediated & some cracks remediation is on going. Dampness found some position of the building. 16-02-2023: During visit date non structural wall crack found on the building. some cracks they are remediated & some cracks remediation is on going. Dampness found some position of the building.</p>

সংযুক্তিমূহু (১২)

