

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	
ঠিকানা Nishchintapur, Savar, Dhaka	
কারখানার কোড DHK045	
কালার কোড	
মলায়েনের ধরণ কাঠামোগত মলায়ন	প্রব্যবঙ্গানের জারিখ ২৭–১১–২১১২

ল্যায়নের ধরণ	: কাঠামোগত মূল্যায়ন	পর্যবেষ্ফণের তারিখ:	२१-०৮-२०२३
. পর্ববেষ্ণণ			
পরিদর্শন পর্ববেচ্ছণ ক্যাপ আইটেম ক্যাটাগরি			
১.১. কাৰ্যক্ৰম	ī		
কার্যক্রম সুপারিশের তখ্যসূত্র	Building engineer to draw up plans fo	r water proofing and drainage for the	e roof.
কারখীনার কার্যক্রম	We have taken action and completed প্রযোগ্য নয়	this issue.	
্র প্রাণেশন চুডান্ত সমশ্রসীমা	- 역(시에) 해당		
সংশোধিত সময়সীমা	07-07-7940		
অগ্রগতির অবস্থা	সংশোধিত		
মন্তব্য	CVV Date- 27/12/2020: The factory with proper rain water drainage systetaken regarding this issue. On 26.08. water drainage system has completed drainage system was found during in	em. On 07/06/2021:Remedial action 2021: Roof water proofing with proped d 27/08/2022: Proper water proofing	has been er rain
সংযুক্তি × ×	সমূহ (२)		

২. পর্যবেষ্ণণ

পরিদর্শন No proper roof drainage and water proofing
ক্যাপ
আইটেম
ক্যা টা গরি
ויוו וטו(ז
২.১. কাৰ্যক্ৰম
<.১. শাক্ষ
কাৰ্শক্ৰম Install water proofing and drainage system.
সুপারিশের
ভিশ্যসূত্র
কার্থানার
We have taken action and completed this issue.
অগ্রাধিকার প্রযোগ্য নর
<u>চুড়ান্ত</u>
प्रकार प्रमुखान -
সংশোধিত
न्यस्योमा 👸 🐃 💮 💮
অগ্রগতির সংশোধিত
অবস্থা
CVV Date – 27/12/2020: The factory has been completed its roof water proofing
with proper rain water drainage system. On 07/06/2021:Remedial action has been
মন্তব্য taken regarding this issue. On 26.08.2021: Roof water proofing with proper rain
water drainage system has completed 27/08/2022: Proper water proofing and
drainage system was found during inspection date.
The Trans.
_માં ત્રુષ્કિત્રમૂર્શ (૨)
x x

৩. পর্যবেষ্ষণ

পরিদর্শন পর্ববেষ্ক্রণ	xposed reinforcement
ক্যাপ আইটেম ক্যাটাগরি	
[क्रालानान]	
৩.১. কাৰ্যক্ৰ	ম
কাৰ্যক্ৰম	Building Engineer need to check the exposed reinforcement and suggest a corrective action as required.
সুপারিশের ভখ্যসূত্র	
কার্থানার কার্যক্রম	we have taken action and completed this issue.
<u>অগ্রাখিকার</u>	প্রযোগ্য নয়
চুড়ান্ত সময়সীমা	
সংশোধিত সময়সীমা	02-02-2290
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	CVV Date- 27/12/2020: During the visit, There is no exposed reinforcement is found on the roof floor of the building. On 07/06/2021:Remedial action has been taken regarding this issue. On 26.08.2021: During the visit, There is no exposed reinforcement is found on the roof floor of the building. 27/08/2022: No Exposed reinforcements were found during inspection date.
সংযুক্তি × ×	সমূহ (२)

৪. পর্যবেষ্ফণ

A TOTAL	
পরিদর্শন পর্ববেষ্কণ	xposed reinforcement
ক্যাপ	
আইটেম	
ক্যাটাগরি	
৪.১. কাৰ্যক্ৰয	ম
কাৰ্যক্ৰম	Carry out any remedial actions as directed by the Building Engineer.
সুপারিশের	, ,
ভূখ্যসূত্র	
কার্খানার	We have taken action and completed this issue.
কাৰ্যক্ৰম	·
	থিযোগ্য ন্য
চুডান্ড সমশ্রসীমা	
সংশোধিত সময়সীমা	02-02-2290
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	CVV Date- 27/12/2020: During the visit, There is no exposed reinforcement is found on the roof floor of the building. On 07/06/2021:Remedial action has been taken regarding this issue. On 26.08.2021: During the visit, There is no exposed reinforcement is found on the roof floor of the building. 27/08/2022: No Exposed reinforcements were found during inspection date.
সংযুক্তি × ×	সমূহ (२)

৫. পর্ববেষ্ণণ

পরিদর্শন পর্শবেষ্ফণ	Sheds do not appear on drawings
ক্যাপ আইটেম ক্যাটাগরি	ī

Building to prepare as built drawings. Drawings to be submitted to authorities for approval.

৫.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম

	approvai.
সুপারিশের তখ্যসূত্র	
কার্থানার কার্বক্রম	We will engage a building engineer to prepare as built drawings. Drawings will be submitted to authorities for approval.
অগ্রাধিকার	প্র্যোগ্য ন্য
চুডান্ড সময়সীমা	ob-ob-2o59
সংশোধিত সময়সীমা	07-07-790
অগ্রগতির অবস্থা	সংশোধিত
ম ন্তব্য	CVV Date- 27/12/2020: As-built drawings have been prepared through DIFE non-listed consultancy firm. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021: The drawing of Sheds is appear on as built architectural drawing and its specification found on structural drawing. On 26.08.2021: The drawing of Sheds is appear on as built architectural drawing and its specification found on structural drawing. 27/08/2022: Sheds were appear on as built architectural drawing and its specification found on structural drawing during inspection date.
সংযুক্তি ×	নমূহ (১)

৬. পর্যবেষ্ণণ

পরিদর্শন পর্ববেষ্ডণ	Non engineered connection and bracing system
ক্যাপ আইটেম ক্যাটাগরি	

৬.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম	The connection of steel structure needs to be checked by building engineer and the bracing system is required to ensure the stability of the structure.
সুপারিশের ভখ্যসূত্র	and braining dysterm to require the critical of the state
কার্খীনার কার্শক্রম	We will engage a building engineer to obseve the connection of steel structure to check the bracing system to ensure the stability of the structure.
<u>অগ্রা</u> খিকার	প্রযোগ্য নয়
চূড়ান্ত সমশ্বসীমা	ob-ob-2o54
সংশোধিত সময়সীমা	07-07-790
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	CVV Date- 27/12/2020: The connection of steel structure have been checked through DIFE non-listed consultancy firm. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021: The connection of steel structure have been checked through consultancy firm. Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm. Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. 27/08/2022: The DEA report has received approval from RSC. As Built drawing and retrofit drawing were found on site during inspection date.
সংখ্যুক্ত ×	मभूर (२)

৭. পর্যবেষ্ফণ

পরিদর্শন পর্ববেষ্ণণ	Non engineered connection and bracing system
ক্যাপ	
অ।খ্ছেন ক্যাটাগরি	

.১. কাৰ্যক্ৰম	
. o. 1114-	
কাৰ্যক্ৰম	Carry out any remedial actions as directed by the Building Engineer.
সুপারিশের	
ভখ্যসূত্র	
কারখানার কার্বক্রম	We will engage a building engineer to obseve the connection of steel structure to check the bracing system to ensure the stability of the structure and carry out an remedial actions as directed by the Building Engineer.
অগ্রাধিকার	প্রযোগ্য নর
চুডান্ড সমশ্বসীমা	ob-20-2029
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
মন্ত ব্য	CVV Date- 27/12/2020: The remedial action has been completed by Building Engineer but the consultancy firm is DIFE non-listed. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021:The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof.Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof.Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. 27/08/2022: The DEA report has received approval from RSC. As Built drawing and retrofit drawing were found on site during inspection date.