

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তখ্য

কারখানার নাম	লিউ ফ্যাশন লিমিটেড
ঠিকানা	Meharabari, Hazir Bazar, Valuka, Mymensing,
কারখানার কোড	MYM003
কালার কোড	

মুল্যায়নের ধরণ: কাঠামোগত মুল্যায়ন	পর্যবেষ্ফণের তারিখ: 🕒
১. পর্যবেষ্ণণ	

পরিদর্শন পর্শবেষ্ <u>ড</u> ণ	Moderate overstress has been found in edge and corner steel columns.
ক্যাপ আইটেম ক্যাটাগরি	

কাৰ্যক্ৰম	Factory Engineer to review design, loads and columns stresses in area identified above.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	We will appoint consultants to review design, loads and columns stresses in identified area soon.
<u> অগ্রা</u> খিকার	প্র্যোগ্য নয়
চুডান্ত সময়সীমা	@o-o>- <o\\$< td=""></o\\$<>
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	15.03.2021: They have done reviews of their designs and drawings according to the instructions. They have already finished what was needed to be done. As a result, they have received no color certificate from ACCORD/RSC.

	Produce and actively manage a loading plan for all floor plates within the factory
	giving consideration to floor capacity and column capacity.
সুপারিশের তখ্যসূত্র	
কারখানার কার্বক্রম	We will appoint consultants to Produce and actively manage a loading plan for all floor plates within the factory giving consideration to floor capacity and column capacity soon.
<u> অগ্রাখিকার</u>	
চুডান্ড সমর্মীমা	29-05-5029
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	15.03.2021: They have done reviews of their designs and drawings according to the instructions. They have already finished what was needed to be done. As a result, they have received no color certificate from ACCORD/RSC.