

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার

শ্রম ও কর্মসংস্থান মন্ত্রণাল্য কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

## ক্যাপ পর্ববেষ্ফণের তথ্য

	শাবাব ফেব্রিক্স লি:
ঠিকানা	Bashil, Hazirbari, Bhaluka, Mymensingh-2240
কারখানার কোড	MYM004
কালার কোড	

া: কাঠামোগত মূল্যাশ্বন	প্রবেক্ষণের জার্থ:	
পরিদর্শন পর্শবেষ্ণ্ডণ		
ন		
Factory Engineer to review structural design of identified Building 1 columns giving consideration to column slenderness. The factory to carry out necessary steps as per suggestion of the factory engineer regarding slender columns.		
Action has been taken		
প্রযোগ্য নয়		
२०-०७-२०५१		
07-07-7940		
চলমান		
No design report has been found on site.Water ponding has been observed on roof top, found dampness on different location, non structural cracks have been observed on site. Non engineering stair has been observed on site.		
	ender Column  Factory Engineer to review structural design of ic consideration to column slenderness. The factory per suggestion of the factory engineer regarding  Action has been taken প্রেৰোজ্য লয় ২০-০৩-২০১৭  চলমাল  No design report has been found on site.Water p top, found dampness on different location, non s	