

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার

শ্রম ও কর্মসংস্থান মন্ত্রণাল্য কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোভন কর্মপরিবেশ; গড়ে জুলবে স্মার্ট বাংলাদেশ"

## ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	ক্যাপিটাল ফ্যাশনস লিঃ
ঠিকালা	Dilan Complex (Building-02), Dhaka Road, Chandona Chawrasta, Gazipur-1702.
কারখানার কোড	<b>GZP</b> 063
কালার কোড	

মূল্যায়নের ধরণ: বৈঘুতিক মূল্যায়ন পর্ববেষ্কণের তারিখ: ১৬-০২-২০২৩ ১. পর্যবেষ্ফণ পরিদর্শন | Location-Office - Electrical Single Line Diagram was available but not appropriate. পর্যবেষ্ণণ however concerned person knew about overall electrical system in the factory. ক্যাপ আইটেম ক্যাটাগরি ১.১. কাৰ্যক্ৰম 1. Provide updated SLD matching the existing installation at the factory. 2. SLD to কাৰ্যক্ৰম indicate exact positions of all points of switch boxes and other outlets. 3. SLD to be approved by the engineer-in-charge. সুপারিশের ভখ্যসূত্র কারখানার Action has been taken and work is under process. কাৰ্যক্ৰম **অগ্রাধিকার** ৬ মাস চড়ান্ড 27-03-3029 **স**ময়সীমা সংশোধিত 07-07-7290 সময়সীমা অগ্রগতির চলমান অবস্থা 20/10 /2020 (CVV-1): As built and proposed Electrical Single Line Diagrams are submitted to DIFE for approval on 31 July 2019. 04-01-2021 (CVV-2): Electrical Single Line Diagram was not available but they have DIFE submission received copy. 13-04-2021 (CVV-3): As built and proposed Electrical Single Line Diagrams are submitted to DIFE but does not match entirely with the existing system. 19-মন্তব্য 08-2021 (CVV-4): SLD was available during inspection and it was reviewed for coupled of times and last review submission was on 16-03-2021. 03-08-2022: SLD was available during inspection and it was reviewed for coupled of times and last review submission was on 16-03-2021. 16-02-2023: SLD was available during inspection and it was reviewed for coupled of times and last review submission was on 16-03-2021. সংযুক্তিসমূহ (৪)

## 

boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available or Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not	১. কাৰ্যক্ৰম	
জ্ঞাসুত্র কাৰখানাৰ কাৰ্যক্তম  Action has been taken and work is under process.  জ্ঞাধিকাৰ ৬ সপ্তাহ  চূড়ান্ত সম্প্ৰমীমা  সংশোধিত সম্প্ৰমীমা  জ্ঞান্তিৰ অবস্থা  20/10/2020 (CVV-1): Wiring diagram/ circuit list is not available on Distributi boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available on Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not	কাৰ্যক্ৰম	
মাধ্যম Action has been taken and work is under process.  অগ্রাধিকাৰ ৬ সপ্তাহ  চূড়ান্ত মাধ্যমীমা  মংশোধিত মাধ্যমীমা  অগ্রাতিব অবস্থা  20/10/2020 (CVV-1): Wiring diagram/ circuit list is not available on Distributi boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available on Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not	~	
চুড়ান্ত সমরসীমা সংশোধিত সমরসীমা অঞ্জাতির অবস্থা  20/10/2020 (CVV-1): Wiring diagram/ circuit list is not available on Distributi boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available on Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not		Action has been taken and work is under process.
সমধ্যসীমা মাংশােশিজ সমধ্যসীমা অঞ্জান্তিৰ অবস্থা  20/10/2020 (CVV-1): Wiring diagram/ circuit list is not available on Distributi boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available on Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not	<u> অগ্রাধিকার</u>	৬ সপ্তাহ
সমশ্বসীমা শ্বিষ্ঠা শ্বিষ্টা শ্বিষ্টা শ্বিষ্টা শ্বিষ্টা শ্বিষ্টা শ্বিষ্টা শ্বিষ্টা শ		20-20-203&
প্রবাধী  20/10/2020 (CVV-1): Wiring diagram/ circuit list is not available on Distributi boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available or Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not	সমশ্রসীমা	%®-08-₹0₹®
boards. 04-01-2021 (CVV-2): Wiring diagram/ circuit list was not available or Distribution boards. 14-04-2021 (CVV-3): Circuit list was not available on Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not		শুরু হ্রানি
	<b>মন্ত</b> ব্য	Distribution Boards but as built SLD is there at site and most of the complaints works are done. On 19-08-2021 (CVV-4): Wiring diagram/ circuit list was not available on Distribution Boards during inspection. 03-08-2022: Wiring diagram/ circuit list was not available on Distribution Boards during inspection. 16-02-2023 Wiring diagram/ circuit list was not available on Distribution Boards during