



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার  
শ্রম ও কর্মসংস্থান মন্ত্রণালয়  
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোভন কর্মপরিবেশ;  
গড়ে তুলবে স্মার্ট বাংলাদেশ"

কাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	তুইয়া
ঠিকানা	Rupshi, Rupganj, Narayanganj
কারখানার কোড	NRYO44
কালার কোড	

মূল্যায়নের ধরণ: [কাঠামোগত মূল্যায়ন](#) পর্যবেক্ষণের তারিখ: ১২-০২-২০২৩

**১. পর্যবেক্ষণ**

পরিদর্শন পর্যবেক্ষণ	Steel or temporary structure not conforming to Type-I construction on Roof-top of building.
কাপ আইটেম ক্যাটাগরি	

**১.১. কার্যক্রম**

কার্যক্রম	Remove temporary structure from roof top
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	We have already removed structure from roof top
অগ্রাধিকার	প্রযোজ্য নয়
চূড়ান্ত সমন্বয়সীমা	০৬-০৮-২০২২
সংশোধিত সমন্বয়সীমা	-
অগ্রগতির অবস্থা	চলমান
মন্তব্য	04.10.2020: Found temporary structure but they were removed half portion. 25-01-2021: The factory authority did not agree to remove full portion of steel temporary structure, yet we found half portion already removed. 03.09.2022: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion. 12.02.2023: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion.

সংযুক্তিসমূহ ( ৪ )

