

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

| কারখানার নাম | <u>তুই</u> য়া |
|--------------|------------------------------|
| ঠিকানা | Rupshi, Rupganj, Narayanganj |
| কারখানার কোড | NRY044 |
| কালার কোড | |

| পাৰ (কাড | | পর্যবেষ্ণণের তারিখ: ১২–০২–২০ | |
|-------------------------------------|--|--|--|
| <u>্যান্ডোন সম্</u> । পর্ববেষ্কণ | : কাঠামোগত সুল্যান্নন | 17(नक(ग्रेन शाम्र: ३२-०२-२० | |
| | | ming to Type-I construction on Roof-top of | |
| ১.১. কাৰ্যক্ৰম | | | |
| কাৰ্যক্ৰম | Remove temporary structure from roof top | | |
| সুপারিশের তথ্যসূত্র | , | | |
| কার্থানার কার্শক্রম | We have already removed structure from roof top | | |
| | প্রযোগ্য নর | | |
| চুডান্ত সমর্মীমা | o № – o ₽ – ₹ o ₹ ₹ | | |
| সংশোধিত সময়সীমা | _ | | |
| অগ্রগতির অবস্থা | চলমাল | | |
| মন্তব্য | 01–2021: The factory authority did not temporary structure, yet we found have not engineering Steel shed or temporary visit day which are not incorporate in 12.02.2023: Non engineering Steel shroof top during visit day which are not removed half portion. | re but they were removed half portion. 25- ot agree to remove full portion of steel alf potion already removed. 03.09.2022: Non structure has been found on roof top during a DEA report. They were removed half portion. ned or temporary structure has been found on ot incorporate in DEA report. They were | |
| সংযুক্তি × × | সমূহ (8) ☑ x | | |