

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তখ্য

কারখানার নাম	ক্রস লাইন ওভেন এ্যাপারেলস লিঃ
ঠিকানা	Sharifpur, Haricne (Left side) National University, Gazipur Sadar, Gazipur
কারখানার কোড	GZP 078
কালার কোড	

মূল্যামনের ধরণ: কাঠামোগত মূল্যামন	পর্ববেষ্ফণের তারিখ: ৩০–০৫–২০২২
১. পর্ববেষ্কণ	

পরিদর্শন পর্ববেষ্ণ	Existing structure do not match with Structural Drawing. Corner column dimension ismeasured 15 x15 on field whereas structural drawing shows 18 x18 corner column. Furthermore, the building havecantilevers on three sides in contrary to the drawing.
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কাৰ্যক্ৰম	.১. কার্যক্রম		
কাৰ্যক্ৰম	Building Engineer to survey column locations and compare with structural drawings. Updated drawings to be prepared showing the correct as constructed layout.		
সুপারিশের তখ্যসূত্র			
কার্যথানার কার্যক্রম	We will be assign with design and consultant firm and they will complete		
অগ্রাধিকার	৬ মাস		
চূড়ান্ত সময়সীমা	0 @ - 0 < - < 0 % 9		
সংশোধিত সময়সীমা	07-07-7940		
অগ্রগতির অবস্থা	সংশোধিত		
মন্তব্য	30.12.2020: They have done retrofitting taking ACCORD/RSC's permission. This NC, incorrect information of having 15"x15" and drawing showing 18"x18" has been corrected. Since they have done retrofitting their column sizes now upgraded to 23"x23" (24"x24" including the plaster). But they didn't submit the drawings to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test report later. They have done maximum of their work according to ACCORD/RSC standards. 30–05–2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didn[]t submit any of the documents to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test report later. They have done maximum of their work according to ACCORD/RSC standards.		
সংযুক্তি × ×	মমূহ (8) ×		

account the factory design imposed loading and the as built structure. সুপানিশেন তথ্যসূত্ৰ কানখনান কাৰ্যক্ৰম We will be assign with design and consultant firm and they will complete অগ্ৰাধিকান চুড়ান্ত সমস্বীমা সংশাধিত সমস্বীমা অগ্ৰগতিন অবস্থা 30.12.2020: The cantilevers of this building which were not included in the drawings are nov included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didn test and they have done it too but they will receive the test	২. কাৰ্বক্ৰম	
কাৰ্শানাৰ কৰ্মিক We will be assign with design and consultant firm and they will complete অগ্রাধিকাৰ চূড়ান্ত মন্মনীমা মংশাধিত মনমনীমা অগ্রাভিব অবস্থা 30.12.2020: The cantilevers of this building which were not included in the drawings are nov included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didnlt submit any of the documents to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test	কাশক্রম	
ম্বাধিকার ত্তিত্তি মন্ত্রমীমা মংশোধিত মন্ত্রমীমা অঞ্চাতির অবস্থা 30.12.2020: The cantilevers of this building which were not included in the drawings are nov included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didn test and they have done it too but they will receive the test		
হুড়ান্ত সমরসীমা কাংশাধিত সমরসীমা ব্যাহান্ত ব্যাহান্ত সমরসীমা ব্যাহান্ত ব্যাহান্ত মান্ত ব্যাহান্ত ব্যাহান	কার্থানার কার্বক্রম	We will be assign with design and consultant firm and they will complete
শ্বন্ধনীমা শংশাধিত শ্বন্ধনীমা অগ্রগতির শ্বন্ধা 30.12.2020: The cantilevers of this building which were not included in the drawings are nov included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didn to submit any of the documents to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test	<u> অগ্রা</u> খিকার	
মান্যসীমা মান্যসীমা মান্যসীমা মান্যসীমা মান্যসীমা মান্যমা ম		0/9-02-20%9
30.12.2020: The cantilevers of this building which were not included in the drawings are nov included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didnlt submit any of the documents to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test		07-07-7940
included and were found on the as-built structural and architectural drawing. 30-05-2022 (CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didnlt submit any of the documents to DIFE. According to ACCORD/RSC, they need to do another soil test and they have done it too but they will receive the test		সংশোধিত
report later. They have done maximum of their work according to ACCORD/RSC standards.	মন্তব্য	(CCVV): They have done retrofitting taking ACCORD/RSC's permission. As they are a member of ACCORD/RSC(ID: 10055), they have done DEA, design drawings and also load plans. But they didn[]t submit any of the documents to DIFE. According to ACCORD/RSC,
	X	X X