

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

	এফ আর এম ফ্যাশন হাউছ লি:
ঠিকানা	226 Singair Road, Hemayetpur, Savar, Dhaka
কারখানার কোড	DHK217
কালার কোড	

ल्यायलब भवनः	কাঠামোগত মুল্যায়ন	পর্ববেষ্ফণের তারিখ: ১৮–০৫–২০২
. পর্ববেষ্ফণ		
পরিদর্শন পর্ববেষ্ক্রণ	hly stressed column	
ক্যাপ আইটেম ক্যাটাগরি		
১.১. কাৰ্যক্ৰম		
ফাশক্রম a	actory Engineer to review design, lo	ads and columns stresses in area identified
সুপারিশের তথ্যসূত্র		
কার্থানার কার্যক্রম		
অগ্রাধিকার প্র	্থিছা ন্য	
চুড়ান্ত সমশ্রসীমা	-	
거허쥐거 허	7-07-790	
অগ্রগতির অবস্থা	াংশোধিত	
re c fa d মন্তব্য w d S T	emediation works under ACCORD su completion certificate with all design actory management is instructed to drawings with soft copy CD and ACCO within 22/03/2021. On Visit Date 31/ done all Structural remediation works Structural CAP completion certificate They've submitted all ACCORD appro-	y management have done all Structural pervision. ACCORD's Structural CAP & drawings found during visit. Now the submit all ACCORD approved design & DRD CAP completion certificate to DIFE RCC (08/2021: The factory management have under ACCORD supervision. ACCORD's with all design & drawings found during visit. Wed structural design & drawings to DIFE RCC nagement is waiting for taskforce decision

২. পর্যবেষ্ণণ

পরিদর্শন পর্ববেষ্ডণ	Highly stressed column
ক্যাপ আইটেম	
ক্যাটাগরি	1

Verify in-situ concrete stresses by 100mm dia. cores from C2 Column.

২.১. কাৰ্যক্ৰম কাৰ্যক্ৰম

সুপারিশের তখ্যসূত্র

কারখানার	
কাৰ্যক্ৰম	
অগ্রাধিকার	প্রযোজ্য ন্য
চুডান্ত	
<u> </u>	
সংশোধিত	02-02-2290
সময়সীমা	້ ລັ້ນ ພັບ ^ຈ
<u>অগ্রগতির</u>	সংশোধিত
অবস্থা	1// 11/10
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৩. পর্যবেষ্ষণ

	রিদর্শন র্শবেষ্ষণ	ghly stressed column
	্যাপ াইটেম	
ক	<u> </u>	
	•	
৩	.১. কাৰ্যক্ৰ	ন
		A Datail Engineering Assessment of Factors to be seened as attached
	কাৰ্যক্ৰম	A Detail Engineering Assessment of Factory to be commenced, see attached Scope.
	সুপারিশের	
	ভ৾খ্যসূত্র	
	কার্খানার	
	কাৰ্যক্ৰম	
	অগ্রাধিকার	প্রযোগ্য নর
	চুড়ান্ত সময়সীমা	
	সংশোধিত সমশ্রসীমা	07-07-7940
	<u>শ্ব রশালা</u> অগ্রগতির	
	শব্রশাত্র অবস্থা	সংশোধিত
	মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC. 18-05-2022 (CCVV): 4 nos. ancillary structures (Dining Shed, Generator Room, Admin Room and Inspection Room) have been found in the factory premises., which have only as-built drawing without any DEA report.
	× ×	X X

৪. পর্যবেষ্ণণ

পরিদর্শন পর্শবেষ্ষণ	Highly stressed column
ক্যাপ আইটেম	
ক্যাটাগরি	

৪.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম	Produce and actively manage a loading plan for all floor plates within the factory giving consideration to floor capacity and column capacity.
সুপারিশের তথ্যসূত্র	
কার্থানার কার্যক্রম	
অগ্রাধিকার চুডান্ত	প্র্যোগ্য ন্য
সম্বসীমা সংশোধিত	
সম্যুসীমা অগ্রগতির	07-07-7940
শুগ্রুগাভূর শুবৃ স্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৫. পর্ববেষ্ণণ

পরিদর্শন পর্ববেষ্ডণ	Highly stressed column
ক্যাপ আই্টেম্	
ক্যাটাগরি	

<u> ৫.১. কাৰ্যক্র</u> ু	₹ <u> </u>
কাৰ্যক্ৰম	Detail Engineering Assessment to be completed.
সুপারিশের	
ভখ্যসূত্ৰ	
কারখানার কার্যক্রম	
	প্রযোগ্য নয়
চুডান্ড সময়সীমা	_
সংশোধিত সময়সীমা	02-02-2290
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৬. পর্যবেষ্ফণ

পরিদর্শন পর্ববেষ্ফণ	Highly stressed column
ক্যাপ আই্টেম্	
ক্যাটাগরি	ৰ্বজন

আইটেম ক্যাটাগরি	
৬.১. কাৰ্যক্ৰঃ	ন
কাৰ্যক্ৰম	Continue to implement load plan.
সুপারিশের ভখ্যসূত্র	
কারখানার কার্বক্রম	
	প্রযোগ্য নর
চুড়ান্ত সময়সীমা	_
সংশোধিত সময়সীমা	02-02-2290
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৭. পর্ববেষ্ফণ

পরিদর্শন পর্শবেষ্ফণ	Lateral Stability System Not Apparent
ক্যাপ আইটেম ক্যাটাগরি	

৭.১. কাৰ্যক্ৰম

ন.১. কাশক্রম	l .
কাৰ্শক্ৰম	Factory Engineer to review design, loads and punching capacity for slabs. Carry out any remedial actions as directed by the Building Engineer for lateral stability
	system.
সুপারিশের তথ্যসূত্র	
কার্থানার কার্যক্রম	
	প্রযোগ্য নয়
চুডান্ত সমশ্বসীমা	_
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC. 18-05-2022 (CCVV): Possible over loading has been found at ground floor.
সংবক্তিসমূহ (২)	

সংযুক্তিসমূহ (২) <a>×