



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখালা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

মুরগ্কা নিবন্ধন নিশ্চিত করণ

ক্যাপ পর্যবেক্ষণের তথ্য

কারখালার নাম	রোজ সুয়েটোর লিঃ
ঠিকানা	Mogarkhal, Bijoy Sarak, Joydevpur, Gazipur
কারখালার কোড	GZP289
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন	পর্যবেক্ষণের তারিখ: ২৯-০৩-২০২৩
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	No proper roof drainage and water proofing
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম	
কার্যক্রম	Proper roof drainage system and water proofing need to be implemented as per guidance of building engineer.
সুপারিশের তথ্যসূত্র	
কারখালার কার্যক্রম	We will engage a building engineer to implement proper roof drainage system & water proofing. 13th December 2020:
অধ্যাধিকার	প্রয়াজ্যা নব
চূড়ান্ত সময়সীমা	০৭-১০-২০২৭
সংশ্লাধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	Water ponding has been observed on roof during site visit. 13th December 2020: Water ponding mark has been observed on roof. 06.06.2021: Water ponding on the rooftop was observed. 3rd August 2022: During visit day water ponding on the rooftop was observed. 29.03.2023: During visit day water ponding on the rooftop was observed.
সংযুক্তিমূল্য (৮)	
<input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	