

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	ৰোজ সুমেটাৰ লিঃ
ঠিকানা	Mogarkhal, Bijoy Sarak, Joydevpur, Gazipur
কারখানার কোড	GZP 289
কালার কোড	

নুল্যায়নের ধর	গ: কাঠামোগত মুল্যারন পর্ববেক্ষণের তারিথ: ২৯–০৩–২০২৬
় পর্ববেষ্ণণ	
পরিদর্শন পর্ববেষ্ক্রণ	o proper roof drainage and water proofing
ক্যাপ আইটেম ক্যাটাগরি	
১.১. কাৰ্যক্ৰ	न
কাৰ্যক্ৰম	Proper roof drainage system and water proofing need to be implemented as per guidance of building engineer.
সুপারিশের ভিখ্যসূত্র	
কার্খানার কার্শক্রম	We will engage a building engineer to implement proper roof drainage system & water proofing. 13th December 2020:
1	প্রধোজ্য নয়
চুডান্ড সমর্মীমা	09-50-7059
সংশোধিত সময়সীমা	02-02-2290
অগ্রগতির অবস্থা	চলমাল
মন্তব্য	Water ponding has been observed on roof during site visit. 13th December 2020: Water ponding mark has been observed on roof. 06.06.2021: Water ponding on the rooftop was observed. 3rd August 2022: During visit day water ponding on the rooftop was observed. 29.03.2023: During visit day water ponding on the rooftop was observed.
সংযুক্তি × ×	সমূহ (8) × ×