

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

## ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	মাসকো পিকাসো লিঃ
ঠিকানা	318, KHAPARI ROAD, SHATAISH, TONGI, Gazipur
কারখানার কোড	<b>GZP</b> 218
কালার কোড	

মুল্যামনের ধরণ: কাঠামোগত মুল্যামন পর্ববেক্ষণের তারিখ: ১৭–				<u> </u>	
১. পৰ্ববে					
পরিদর্শন পর্ববেষ্কণ Soil test report and floor load plan were not available.					
ক্যাপ আইটেম ক্যাটাগরি					
১.১. কাৰ্যক্ৰম					
কাৰ্যক্ৰম Building engineer should investigate the soil should prepare a floor load plan.			e soil vicinity to the structure. He als	50	
সুপারিশের তথ্যসূত্র					
1 1 a 1		Soil test report has been prepared and floor load plan will be prepared by the Engineer.			
অগ্রাধিকার		প্রযোগ্য নয়			
प्रभेर	চুড়ান্ত সময়সীমা ০২–০২–২০১৭				
সংশোধিত সমশ্রসীমা <sup>১১ – ১১ – ১১</sup> ৭ ০		07-07-7940			
<b>অগ্রগতির</b> অবস্থা					
government author মন্তব্য were found in facto nominated by DIFE. for approval as soon		government authority, as built architec were found in factory. Load plan found nominated by DIFE. 17/11/2022: All De for approval as soon as possible.	st report, Material test report, building approval plan from local rity, as built architectural drawing, as built structural drawing bry. Load plan found but not vetted. Factory consultant were not 17/11/2022: All Design & Drawing should be submitted to DIFE n as possible.		
সং <sup>ন</sup> ×	যুক্তি≀ ≚	মমূহ (8) <b>×</b> ×			