



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

শ্রমস্বাধীন মানুষের অধিকার, বৈষম্যহীন
বাংলাদেশের অঙ্গীকার

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	শাদ নিটওয়ার লি:
ঠিকানা	Arabari, Mouchak, Gazipur
কারখানার কোড	GZP294
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন পর্যবেক্ষণের তারিখ: ১১-০৪-২০২৩

১. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	Exposed rebar has been found on roof top.
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম

কার্যক্রম	All of the exposed rebars to be coated with proper weather coating.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	[Whom is going to carry out the recommendation?] [How will the recommendation be carried out?]
অগ্রাধিকার	১ সপ্তাহ
চূড়ান্ত সময়সীমা	০১-০১-১৯৭০
সংশোধিত সময়সীমা	০৫-০৩-২০২৩
অগ্রগতির অবস্থা	চলমান
মন্তব্য	27.09.2020: Exposed rebar has been found on roof top column and stair with coating but not with red oxide. Also the staircase rebars are not coated. 13 January 2021: Exposed rebar has been found on roof top column and stair with coating but not with red oxide. Also the staircase rebars are not coated. 03.06.2021: Exposed rebars were still not painted or coated. 16.08.2022: Roof top column exposed rebars & expose rebar of stair were still not painted or coated. 11.04.2023: Roof top column exposed rebars & expose rebar of stair were still not painted or coated.

সংযুক্তিসমূহ (৪)

