



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখালা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

মুরগ্কা নিবন্ধন নিশ্চিত করণ

ক্যাপ পর্যবেক্ষণের তথ্য

কারখালার নাম	এন আই লিটওয়্যার লি.
ঠিকানা	215/216, Dewandighi, Dewanhat, Chattogram
কারখালার কোড	CHT106
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন	পর্যবেক্ষণের তারিখ: ১৪-০৯-২০২২
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	Water stagnation on roof top
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম	
কার্যক্রম	Water proofing and proper roof drainage system need to be implemented as directed by the guidance of building engineer.
সুপারিশের তথ্যসূত্র	
কারখালার কার্যক্রম	We will engage a building engineer to complete this issue.
অধ্যাধিকার	প্রযোজ্য নথি
চূড়ান্ত সময়সীমা	২৮-৯০-২০৯৭
সংশ্লাধিত সময়সীমা	০৯-০৯-১৯৭০
অগ্রগতির অবস্থা	চলচাল
মন্তব্য	20/02/2020: Roof Drainage system found ok during inspection and water proofing has been implemented. On 23.08.2020: No sign of water stagnation during inspection. Water proofing has been implemented. On 05.11.2020: Water proofing has been implemented. On 03.02.2021: Task completed. On 03.06.2021: Task already completed. On 16.08.2021: Water proofing & roof drainage found ok. 14/09/2022: Water stagnation was observed on roof top during inspection date.
মংযুক্তিসমূহ (২)	
<input checked="" type="checkbox"/> <input checked="" type="checkbox"/>	