



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

শ্রমজীবী মানুষের অধিকার, বৈষম্যহীন
বাংলাদেশের অঙ্গীকার

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	তুইয়া
ঠিকানা	Rupshi, Rupganj, Narayanganj
কারখানার কোড	NRYO44
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন পর্যবেক্ষণের তারিখ: ১২-০২-২০২৩

১. পর্যবেক্ষণ

পরিদর্শন পর্যবেক্ষণ	Steel or temporary structure not conforming to Type-I construction on Roof-top of building.
ক্যাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম

কার্যক্রম	Remove temporary structure from roof top
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	We have already removed structure from roof top
অগ্রাধিকার	প্রযোজ্য নয়
চূড়ান্ত সময়সীমা	০৬-০৮-২০২২
সংশোধিত সময়সীমা	-
অগ্রগতির অবস্থা	চলমান
মন্তব্য	04.10.2020: Found temporary structure but they were removed half portion. 25-01-2021: The factory authority did not agree to remove full portion of steel temporary structure, yet we found half portion already removed. 03.09.2022: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion. 12.02.2023: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion.

সংযুক্তিসমূহ (৪)

